

Fix It #1 Cleveland Park -2900 block of Porter Street NW-dead tree removal & graffiti abatement

BEFORE DURING





AFTER



BEFORE




AFTER



Fix It #2 Cleveland Park-3300 block of Connecticut Ave NW-sidewalk repair & graffiti abatement

BEFORE





BEFORE AFTER



























Before:







AFTER



